



Test Report Page 1 of 4 No.: XMHL2004001750OT Date: Apr. 28, 2020

SHANDONG SUNFULL INDUSTRIAL CO., LTD NO.98, TIAN JIN ROAD, ECONOMIC DEVELOPMENT ZONE, PENGLAI, SHANDONG, CHINA

: COMPACT LAMINATE Sample Description Style / Item No. : 8MM 10MM 12MM

As above test item and its relevant information regarding to the submission are provided and confirmed by the applicant. SGS is not liable to either the test item or its relevant information, in terms of the accuracy, suitability, reliability or/and integrity accordingly.

SGS Ref No. : GZIN2004015467MR

Sample Receiving Date : Apr. 20, 2020

Test Performing Date : Apr. 20, 2020 to Apr. 28, 2020

Test Performed : Selected test(s) as requested by applicant

Test Result(s) : For further details, please refer to the following page(s)

Signed for and on behalf of SGS-CSTC Standards Technical Services Co., Ltd. Xiamen Branch

Beck Hong

Authorized Signatory



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at https://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention:To check the authenticity of testing / inspection report & certificate, please contact us at telephone:(86-755) 8307

No.31 Xianghong Road, Xiang'An Torch Industrial Zone, Xiamen, Fujian Province, China 361101 t (86-592) 5766537 中国・福建・厦门・火炬(翔安)产业区翔虹路31号

邮编: 361101 t (86-592) 5766537

f (86-592) 5766460 f (86-592) 5766460

www.sgsgroup.com.cn e sgs.china@sgs.com



Test Report Date: Apr. 28, 2020 Page 2 of 4 No.: XMHL2004001750OT

Summary of Results:


No.	Test Item	Test Method	Result	Conclusion
1	Tensile Strength	ISO 527-1:2019 & ISO 527-2:2012	89.6MPa	/

Note: Pass: Meet the requirements;

Fail: Does not meet the requirements;

/: Not Apply to the judgment.

Original Sample Photo:





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgety or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@gs.com

No.31 Xianghong Road, Xiang'An Torch Industrial Zone, Xiamen, Fujian Province, China 361101 t (86–592) 5766537 f (86–592) 5766460 中国・福建・厦门・火炬(翔安)产业区翔虹路31号

邮编: 361101 t (86-592) 5766537

www.sgsgroup.com.cn f (86-592) 5766460 e sgs.china@sgs.com



Test Report Date: Apr. 28, 2020 Page 3 of 4 No.: XMHL2004001750OT

Test Item: Tensile Strength Sample Description: Plastic part

Test Method: ISO 527-1:2019 & ISO 527-2:2012

Test Condition:

Specimen: Type 1BA

Specimen thickness: 9.80 mm Testing speed: 5 mm/min

Initial distance between grips: 50 mm

Lab Environmental Condition: 23 ± 2 °C, 50 ± 5 % RH


Test Result:

Test Item	Test Result
Tensile Strength	89.6MPa

Note: Test specimens were cut from the sample.

Remark: This test was subcontracted to Guangzhou Branch, SGS-CSTC Co., Ltd.

Test Photo:





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@ggs.com


No.31 Xianghong Road, Xiang'An Torch Industrial Zone, Xiamen, Fujian Province, China 361101 t (86–592) 5766537 f (86–592) 5766460 中国・福建・厦门・火炬(翔安)产业区翔虹路31号

邮编: 361101 t (86-592) 5766537

www.sgsgroup.com.cn f (86-592) 5766460 e sgs.china@sgs.com



Test Report No.: XMHL2004001750OT Date: Apr. 28, 2020 Page 4 of 4



Equipment Information:

Equipment	Model	Equipment No.	Calibration date	Next Calibration date
Universal Testing Machine	Z010	GZMR-PL-E109	2019-11-04	2020-09-02

The testing report/certificate only refers to the sample(s) tested.

End of Report





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgety or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@gs.com

1443, or email: CN.Doccheck@sgs.com

No.31 Xianghong Road, Xiang'An Torch Industrial Zone, Xiamen, Fujian Province, China 361101 t (86-592) 5766537 f (86-592) 5766460 www.sgsgroup.com.cn

中国・福建・厦门・火炬(翔安)产业区翔虹路31号

邮编: 361101 t (86-592) 5766537

f (86–592) 5766460 e

e sgs.china@sgs.com